

**Flood Control Project Maintenance
Levee Inspections**

Fall 2013 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR Erosion Survey

San Joaquin River Basin

RD2058	Overall LMA Rating	Total LMA Miles	* Overall LMA Threshold Percent is less than 10.00%; however, U Rated Miles are present, so the Overall LMA Rating is M instead of A.					
Reclamation District No. 2058 Pescadero	M *	6.71						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.08		0.08	1.19%				
Encroachments					0.08	0.02		
Erosion / Bank Caving		0.01	0.04	0.60%				
<i>Supplemental</i>								
DWR Erosion Survey	0.05		0.05	0.75%				
<i>LMA Totals:</i>	0.13	0.01	0.17	2.53% *	0.08	0.02	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2013 Levee Inspection Results

Reclamation District No. 2058 Pescadero

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			M	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2013 Levee Inspection Results

Reclamation District No. 2058 Pescadero

Waterway			Bank	Unit Miles
Unit No. 01 Paradise Cut			Left	6.71
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			M	
Date of Inspection	05/22/2013 - 05/22/2013		10/29/2013 - 10/29/2013	
DWR Inspector	Maksim Khashchuk		Maksim Khashchuk	
Accompanied By	Greg Pombo		Greg Pombo RD2058	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut				Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End					Start	End	Photo
1			Earthen Levee	Flood Preparedness & Training	WS A Ma		°	°	6
DWR ID: DWR_RD2058_01_s_2013_6									
2			Earthen Levee	Emergency Supplies & Equipment	WS A Ma		°	°	7
DWR ID: DWR_RD2058_01_s_2013_7									
3			Earthen Levee	Operations & Maintenance Manuals	WS A Ma		°	°	9
DWR ID: DWR_RD2058_01_s_2013_9									
4	0.23	0.23	Earthen Levee	Vegetation	LS A/W Ob	V8 : Environmental Requirements. Inspector Comments: Wild rose brush rabbit habitat.	37.804351 ° -121.418433 °	37.804351 ° -121.418433 °	4 Y
DWR ID: DWR_RD2058_01_f_2013_4									
5	0.41	0.44	Earthen Levee	Vegetation	LS C Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	37.803834 ° -121.415720 °	37.803411 ° -121.415268 °	10
DWR ID: DWR_RD2058_01_s_2013_10									
6	0.42	0.42	Earthen Levee	Vegetation	WS C Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Thick vegetation at this point, needs to be removed.	37.803813 ° -121.415578 °	37.803813 ° -121.415578 °	8
DWR ID: DWR_RD2058_01_s_2012_8									
7	0.72	0.72	Earthen Levee	Encroachments	LS A/W Ma	PI : Pipe	37.801807 ° -121.410945 °	37.801807 ° -121.410945 °	3 Y
DWR ID: DWR_RD2058_01_f_2012_3									
8	1.24	1.24	Earthen Levee	Encroachments	CRA/W Ma	PI : Pipe	37.802314 ° -121.401984 °	37.802314 ° -121.401984 °	22 Y
DWR ID: DWR_RD2058_01_s_2012_22									
9	1.72	1.78	Earthen Levee	Vegetation	WS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	37.804333 ° -121.393657 °	37.804615 ° -121.392588 °	961 Y
DWR ID: DWR_RD2058_01_s_2012_961									
10	1.84	1.84	Earthen Levee	Encroachments	LS M En	MA : Material Inspector Comments: Pile of concrete contains rebar on landside slope obstructing visibility and access.	37.804785 ° -121.391524 °	37.804785 ° -121.391524 °	11 Y
DWR ID: DWR_RD2058_01_f_2013_11									
11	2.13	2.13	Earthen Levee	Encroachments	CRA/W Ma	PI : Pipe	37.803903 ° -121.386312 °	37.803903 ° -121.386312 °	23 Y
DWR ID: DWR_RD2058_01_s_2012_23									

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
12	2.15	2.15	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 08/28/2013: No significant change observed. 07/31/2012: Site was visited on 07/26/2012. No significant change observed. A new vertical pipe was installed and concrete blocks left on the site. Dense vegetation is visible at the site. No signs of new leaks or spill from the siphon breaker. 09/02/2011: Site was not visited due to the time limit. 09/22/2010: No significant changes observed. Vegetation downstream, upstream and on the lower slope of the site have been recently sprayed. These areas were also fenced off during the site visit, making it difficult for us to examine the condition of the lower slope. Possible leak or spill from the siphon breaker is creating notches along the slope and developing into a headward erosion. If the problem continues, it will erode the slope and fully expose the pipe to outside elements. 07/23/2009: A possible leak or spill from a siphon breaker is eroding the slope and developing into a headward erosion; a portion of the buried pipe is exposed; the lower slope seems to be lined with chunks of concrete debris or other rock material. [2013 Site ID:RD2058U01RM1.78]	37.803769 ° -121.386341 °	37.803769 ° -121.386341 °	1 Y
13	2.26	2.33	Earthen Levee	Encroachments	LS	M	DT : Ditch	37.803375 ° -121.384196 °	37.803136 ° -121.383078 °	12
DWR ID: DWR_RD2058_01_f_2013_12										
14	2.42	2.42	Earthen Levee	Vegetation	LS	A/W	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry growing on landside toe.	37.802782 ° -121.381413 °	37.802782 ° -121.381413 °	16 Y
DWR ID: DWR_RD2058_01_s_2012_16										
15	2.64	2.64	Earthen Levee	Vegetation	WSA/W	Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry on waterside slope.	37.801962 ° -121.377684 °	37.801962 ° -121.377684 °	63 Y
DWR ID: DWR_RD2058_01_s_2012_63										
16	2.66	2.66	Earthen Levee	Vegetation	WSA/W	Ob	V4 : Elderberries are blocking visibility and flood fight capability.	37.801876 ° -121.377291 °	37.801876 ° -121.377291 °	64
DWR ID: DWR_RD2058_01_s_2012_64										
17	2.67	2.67	Earthen Levee	Vegetation	WSA/W	Ob	V4 : Elderberries are blocking visibility and flood fight capability.	37.801823 ° -121.377068 °	37.801823 ° -121.377068 °	65
DWR ID: DWR_RD2058_01_s_2012_65										
18	2.73	2.73	Earthen Levee	Encroachments	CR	C	PR : Prunings	37.801575 ° -121.375988 °	37.801575 ° -121.375988 °	13
DWR ID: DWR_RD2058_01_f_2013_13										
19	2.76	2.76	Earthen Levee	Vegetation	WSA/W	Ob	V4 : Elderberries are blocking visibility and flood fight capability.	37.801497 ° -121.375586 °	37.801497 ° -121.375586 °	66
DWR ID: DWR_RD2058_01_s_2012_66										
20	2.89	2.89	Earthen Levee	Encroachments	WSA/W	PI	Pipe	37.800894 ° -121.373135 °	37.800894 ° -121.373135 °	24 Y
DWR ID: DWR_RD2058_01_s_2012_24										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut				Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
21	2.94	2.94	Earthen Levee	Encroachments	WS	C En	PR : Prunings	37.800698 ° -121.372396 °	37.800698 ° -121.372396 °	14
DWR ID: DWR_RD2058_01_f_2013_14										
22	3.41	3.41	Earthen Levee	Encroachments	CRA/W	PI : Pipe Ma	Inspector Comments: Drainage discharge.	37.796421 ° -121.366254 °	37.796421 ° -121.366254 °	27
DWR ID: DWR_RD2058_01_s_2012_27										
23	3.57	3.57	Earthen Levee	Vegetation	LS A/W	V4 : Elderberries are blocking visibility and flood fight capability. Ob		37.794396 ° -121.364944 °	37.794396 ° -121.364944 °	68
DWR ID: DWR_RD2058_01_s_2012_68										
24	3.76	3.76	Earthen Levee	Vegetation	WS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Flagged bushes obstructing visibility and access.	37.791856 ° -121.363514 °	37.791856 ° -121.363514 °	974
DWR ID: DWR_RD2058_01_s_2012_974										
25	3.85	3.85	Earthen Levee	Vegetation	WSA/W	V8 : Environmental Requirements. Ma	Inspector Comments: Revegetation site.	37.790807 ° -121.362905 °	37.790807 ° -121.362905 °	20 Y
DWR ID: DWR_RD2058_01_s_2012_20										
26	4.01	4.01	Earthen Levee	Vegetation	LS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry on landside hinge point.	37.789128 ° -121.361042 °	37.789128 ° -121.361042 °	26 Y
DWR ID: DWR_RD2058_01_s_2012_26										
27	4.01	4.01	Earthen Levee	Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability. Ob		37.789096 ° -121.360966 °	37.789096 ° -121.360966 °	69
DWR ID: DWR_RD2058_01_s_2012_69										
28	4.36	4.36	Earthen Levee	Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability. Ob		37.789794 ° -121.354883 °	37.789794 ° -121.354883 °	71
DWR ID: DWR_RD2058_01_s_2012_71										

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
29	4.49	4.53	Supplemental	DWR Erosion Survey	WS	M Ma	Inspector Comments: 08/28/2013: No significant change observed. 07/26/2012: The site has been visited, and no significant change has been observed. 09/02/2011: This site was not visited due to the time limit. 09/22/2010: No significant changes observed. Minor pocket erosions are lined at the lower bank. Two large Oak and Willow trees are on mid-slope and bench. The remaining bench was re-measured and found to be approximately 10 feet. There was no indication of active erosion on site during the site visit. 08/05/2010: Recommended for annual assessment and monitoring of site during flood events, per CLRO. 07/23/2009: No major change observed since last visit; site is a 200-ft. long near-vertical berm erosion; recommend annual assessment and monitoring of erosion site, per CLRO CES Evaluation 2008 Report; Site # is the same site previously reported as RM4.0,LM4.51; previously rated "U". 09/10/2008: Two large trees (2-3' DBH) with partial roots exposed. 2007: Visited site 03/13/2007. [2013 Site ID:RD2058U01RM3.97]	37.789810 ° -121.352490 °	37.789810 ° -121.352490 °	2 Y
DWR ID:										
30	4.82	4.82	Earthen Levee	Erosion / Bank Caving	WS	U Ma	E1 : Note and monitor erosion site. Inspector Comments: The erosion has about a 3 foot vertical cut at the waterside levee toe.	37.785862 ° -121.350303 °	37.785862 ° -121.350303 °	15 Y
DWR ID: DWR_RD2058_01_f_2013_15										
31	5.16	5.16	Earthen Levee	Encroachments	LS	U En	RA : Ramp Inspector Comments: New ramp construction connecting dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.	37.783102 ° -121.345682 °	37.783102 ° -121.345682 °	29 Y
DWR ID: DWR_RD2058_01_s_2012_29										
32	5.37	5.37	Earthen Levee	Encroachments	LS	U En	RA : Ramp Inspector Comments: Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.	37.782268 ° -121.342257 °	37.782268 ° -121.342257 °	30 Y
DWR ID: DWR_RD2058_01_s_2012_30										
33	6.06	6.06	Earthen Levee	Animal Control	CR	C Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.775015 ° -121.335233 °	37.775015 ° -121.335233 °	5
DWR ID: DWR_RD2058_01_f_2012_5										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	4
Start Levee Mile	0.23
End Levee Mile	0.23
Location	Land Side
Category	Earthen Levee
Item	Vegetation

View of the wild rose habitat for the brush rabbit.

mkhashch_f_20131031_703.JPG



Levee Mile Report Line	7
Start Levee Mile	0.72
End Levee Mile	0.72
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of discharge pipe on landside slope.

mkhashch_f_20130923_217.JPG



Levee Mile Report Line	8
Start Levee Mile	1.24
End Levee Mile	1.24
Location	Crown
Category	Earthen Levee
Item	Encroachments

Drainage discharge to Paradise Cut.

mkhashch_f_20130923_223.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	9
Start Levee Mile	1.72
End Levee Mile	1.78
Location	Water Side
Category	Earthen Levee
Item	Vegetation

View if the overgrown vegetation on the waterside slope to be removed.

mkhashch_f_20131031_704.JPG



Levee Mile Report Line	10
Start Levee Mile	1.84
End Levee Mile	1.84
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of the concrete with rebar placed on the landside slope.

mkhashch_f_20131031_705.JPG



Levee Mile Report Line	11
Start Levee Mile	2.13
End Levee Mile	2.13
Location	Crown
Category	Earthen Levee
Item	Encroachments

Drainage discharge to Paradise Cut.

mkhashch_f_20130923_224.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	12
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view of siphon breaker.

SJR2013_RD2058U01RM1.78_3.jpg



Levee Mile Report Line	14
Start Levee Mile	2.42
End Levee Mile	2.42
Location	Land Side
Category	Earthen Levee
Item	Vegetation

03/28/2012 Large elderberry bush on landside slope.

mkhashch_f_20130923_221.jpg



Levee Mile Report Line	15
Start Levee Mile	2.64
End Levee Mile	2.64
Location	Water Side
Category	Earthen Levee
Item	Vegetation

03/28/2012 Large elderberry bush located on waterward slope.

mkhashch_f_20130923_233.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	20
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Irrigation intake from Paradise Cut.

mkhashch_f_20130923_225.jpg



Levee Mile Report Line	25
Start Levee Mile	3.85
End Levee Mile	3.85
Location	Water Side
Category	Earthen Levee
Item	Vegetation

11/08/2011 Revegetation site, cannot trim or cut vegetation in this area.

mkhashch_f_20130923_222.jpg



Levee Mile Report Line	26
Start Levee Mile	4.01
End Levee Mile	4.01
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Elderberry bushes on landside slope.

mkhashch_f_20130923_226.JPG



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	29
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view of the erosion near a tree.

SJR2013_RD2058U01RM3.97_2.jpg



Levee Mile Report Line	30
Start Levee Mile	4.82
End Levee Mile	4.82
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving

View of the erosion at the waterside levee toe.

mkhashch_f_20131031_708.JPG



Levee Mile Report Line	31
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20130923_227.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	31
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20130923_228.jpg



Levee Mile Report Line	31
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20130923_229.JPG



Levee Mile Report Line	32
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 Photo shows existing middle ramp to the levee which has been raised.

mkhashch_f_20130923_230.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	10/29/2013 10/29/2013	Maksim Khashchuk

Levee Mile Report Line	32
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments
11/08/2011 Photo shows view from the levee looking to the left of the middle ramp.	
mkhashch_f_20130923_231.jpg	



Levee Mile Report Line	32
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Completed new ramp constructed by Dairy farmer connecting his barns to the levee.	
mkhashch_f_20130923_232.JPG	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement